

Emergency Response Drill Data Sheet / Report

Type of Drill: FIRE Drill
Facility: Renaissance

Time: 2:30Pm Date: 13/6/2026
Exact Location: N

A - Muster Data:

Event/Operation : Recompletion of Nun-River Well 6	Achieved	Target	Points Scored:	Comment:
Muster start	2:35pm	2:40pm	10	Response was swift
Muster completed	2:45Pm	2:45Pm	10	Reponse time was ok
Muster time	3 Mins	5 minutes (10 points)	10	N/A
Alarm sounded	YES	5 minutes (10 points)	10	A Verbal alarm was raised, followed with a verbal announcement .
Roll call / Head count	YES	YES	10	Head count was carried out and all personnel at the main camp were accounted for .
All persons present	yes	yes	10	All persons were present .

B - Drill Data:

Checked if the entrance to the safe haven was secured.	N/A	N/A	10	N/A
System isolated / shut down as required	N/A	N/A	10	N/A
Relevant parties informed as required.	Yes	10	10	The operational heads were informed of the fire drill.
Fuel source removed if safe to do so.	N/A	N/A	10	N/A
Electrical system isolated as required.	YES	YES	10	The electrical panel switch was switched off to turn down the fire.
A	N/A	N/A	N/A	N/A
Government security personnel on stand by	N/A	N/A	10	N/A
Was the emergency drill communicated to higher security officers/ town in accordance to security reporting protocol?	YES	YES	YES	The OIM for FLB and other higher security officers were informed according to security protocol.

C - Debriefing:

ere personnel on board briefed?	Yes	10	10	The Safety Coach and the Tecon HSE Coordinator debriefed Personnel at the Muster Point B.
re lessons learnt?	Yes	10	10	Personnel were now aware of the Muster Point B.
Max Score	Total score	100	100	

Response	Above average	
Drill score =	100%	
score =	Total point scored = 100	
Further Comments if any:		

At about 14:45hrs, The laundry man raised an alarm of fire in the laundry which was followed with a swift response by the fire team. They moved in with the fire extinguishers and were able to put off the fire.

LOW LIGHTS: The fire wardens came out without their fire suits, the fire wardens had difficulty access the laundry because there was no steps at the entrance door of the laundry. There was no alarm sound but only verbal announcement of the incident was made. Some personnel did not know that there was a muster Point at the main camp.

HIGH LIGHTS: Personnel responded swiftly to the alarm of fire raised by the laundry Man, The fire fighting team also reacted swiftly to the alarm of fire raised. However, though the Muster Point was recently positioned, yet personnel were able to locate and muster at the Muster point.

Follow-up Action items:			
SN	Item	Action party	Severity (S, H, M, L)
1	There is no fire box around the main camp	HSE CORD.	H
2	No emergency alarm / public address system at the main camp.	HSE CORD.	L
3	No steps at the entrance door of the main camp laundry	HSE CORD.	L
4	No muster point signage at the main camp .	HSE CORD.	L
5	No T-Card board at the main camp .	HSE CORD.	L

Action taken/to be taken

A fire box should be provided at the main camp with all fire fighting materials in it.

system should be installed at the main camp.

Steps should be provided at the entrance of the main camp laundry door for easy accessibility.

A second Muster Point Signage should be provided and positioned at the main camp..

A T-C ard board should be provided at the main camp for easy tracking of personnel during emergencies.

HSE CORD. _____

Signature: _____

Date: 13/6/26

SAFETY COACH (RENAISSANCE): SEPRIBO IGBAGIRI

Signature: _____

Date: 13 June 2026

R SUPERVISOR (CHIMA CHUKWU

Signature: _____

Date: 13/6/2026

DSV (RENAISSANCE): _____

Signature: _____

Date: 13/6/26