

Emergency Response Drill Data Sheet / Report

RENAISSANCE
MEDICAL SERVICES COMPANY

Type of Drill: MEDVAC

Time: 2:00pm

Date: 13/7/2026

Facility: Renaissance

Exact Location:

A - Muster Data:

Event/Operation :	Achieved	Target	Points Scored:	Comment:
Recompletion of Nun-River Well 6				
Muster start	2:00pm	2:05pm	10	Response was swift
Muster completed	2:10pm	2:15pm	10	Reponse time was ok
Muster time	5 Mins	5 minutes (10 points)	10	N/A
Alarm sounded	YES	5 minutes (10 points)	10	A Verbal alarm was raised, followed with announcement on PA system
Roll call / Head count	N/A	N/A	N/A	Head count was not carred out
All persons present	N/A	N/A	N/A	Only the first aid team and the Medic was present

B - Drill Data:

Checked if the entrance to the safe haven was secured.	N/A	N/A	10	N/A
System isolated / shut down as required	N/A	N/A	10	N/A
Relevant parties informed as required.	Yes	10	10	The DSV and other units supervisors were informed
Fuel source removed if safe to do so.	N/A	N/A	10	N/A
Electrical system isolated as required.	N/A	N/A	10	N/A
N/A	N/A	N/A	N/A	N/A
Government security personnel on stand by	yes	yes	10	Government security personnel were on stand by to escort the ambulance to the retainership clinic
Was the emergency drill communicated to higher security officers/ town in accordance to security reporting protocol?	N/A	N/A	N/A	N/A

C - Debriefing:

Were personnel on board debriefed?	yes	yes	10	Personnel were debriefed by the DSV, HWO Supervisor, Medic and safety team
Were lessons learnt?	Yes	10	10	The response was swift, though the Medic was far from the scene of the incident but however, two members of the first aid team attended to the IP while waiting the arrival of the medic
Max Score	Total score	100	100	

score =	Total point scored = 100	Drill score = 100%
Further Comments if any:		
A deck personnel who had just resumed work from lunch slumbed on the work deck. Fortunately, one of his colleagues was standing by and he immediately raised a alarm of Help!!!. The alarm raised attention of other crew members who immediately alerted the safety officer who used the PA system to call the Medic		
LOW LIGHTS: 1. The ambulance driver was not available and so took some time for the ambulance to convey the IP to the retainership clinic. 2. IP was crowded by personnel on board trying to know what had happened to him.		
HIGH LIGHTS: The first aiders who came in to the scene displayed high sense of competence. Secondly, the loud sound of the personnel who raised the alarm helped in attracting the attention of other crew members to the scene of the incident. There was a sense of willinness by other crew members to assist		

Item	Action party	Severity (S, H, M, L)	Action taken/to be taken
The ambulance driver was not available	HSE CORD.	H	The ambulance driver should always inform the Medic or the HSE officers of his whereabouts at every given time.
IP was crowded.	HSE CORD/ SAFETY COACH	H	POB should never crowd the IP, so the IP would have access to fresh air for recovery.

JAF CORD. [Signature] Date: 14/7/26
 MEDIC [Signature] Date: [Signature]
 SAFETY COACH (RENAISSANCE): PARKINSON OGBEMEN Signature: [Signature] Date: 14/07/26
 RIG SUPERVISOR [Signature] Date: 14/9/26
 DSV (RENAISSANCE): [Signature] Date: 14/04/2026